

## Knittel, Janette

---

**From:** Long, John <[john.long3@woodplc.com](mailto:john.long3@woodplc.com)>  
**Sent:** Monday, March 23, 2020 3:59 PM  
**To:** Knittel, Janette  
**Subject:** Update on Container Properties

Janette:

A couple of things: During the recent sampling event we discovered that the control transducer in MW-49 had begun to act oddly so the pretreatment system was shutdown. The estimated lifespan of the control transducers was 10-20 years so this one lasted 17 years. A replacement control transducer was ordered from In-Situ and installed last Saturday by Will Young.

While it appeared to be working correctly it had to record 72 hours of data to allow for calculation of the average water level. Once we have confirmed that the transducer is calibrated and working correctly we will return the system to automatic operation. We also purchased a second replacement control transducer for DM-8 for when it fails since it is the same age as the former MW-49 transducer.

I talked with David Blount and he did talk with Elly Hale and Jennifer MacDonald last week. He still planned to talk to Ted Yackulic, and will contact the Anchor QEA representative later this week. David felt that he should take the lead in any discussions of site access since he represents Container Properties directly.

(b) (6)



- John

**John D. Long, LG., L.Hg.**  
Senior Associate Hydrogeologist  
600 University Street, Ste 600  
Seattle, Washington, 98101

D +1 (206) 342-1779  
F +1 (206) 342-1761  
M +1 (206) 713-9499  
E [john.long3@woodplc.com](mailto:john.long3@woodplc.com)

**wood.**

---

This message is the property of John Wood Group PLC and/or its subsidiaries and/or affiliates and is intended only for the named recipient(s). Its contents (including any attachments) may be confidential, legally privileged or otherwise protected from disclosure by law. Unauthorized use, copying, distribution or disclosure of any of it may be unlawful and is strictly prohibited. We assume no responsibility to persons other than the intended named recipient(s) and do not accept liability for any errors or omissions which are a result of email transmission. If you have received this message in error, please

notify us immediately by reply email to the sender and confirm that the original message and any attachments and copies have been destroyed and deleted from your system.

If you do not wish to receive future unsolicited commercial electronic messages from us, please forward this email to: [unsubscribe@woodplc.com](mailto:unsubscribe@woodplc.com) and include "Unsubscribe" in the subject line. If applicable, you will continue to receive invoices, project communications and similar factual, non-commercial electronic communications.

Please click <http://www.woodplc.com/email-disclaimer> for notices and company information in relation to emails originating in the UK, Italy or France.

As a recipient of an email from a John Wood Group Plc company, your contact information will be on our systems and we may hold other personal data about you such as identification information, CVs, financial information and information contained in correspondence. For more information on our privacy practices and your data protection rights, please see our privacy notice at <https://www.woodplc.com/policies/privacy-notice>

---